Lotus
Service Bulletin

CLASS: 111
NUMBER: 1972/014
TYPE: All Europa
Date: 07.08.1972

LOTUS CARS Ltd - NORWICH NORFOLK NOR92W - Tel: WYMONDHAM 3411 - CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman			

Title: Drive Shaft End - Float.

Reason: To advise Dealer personnel of an omission from both the Europa Workshop Manual (Part No. X046 T 0327Z) and the Europa Twin Cam Supplement (Part No. X074 T 0348B).

Action: Under the heading "Transmission" in TECHNICAL DATA of both of the above mentioned publications, please add the following:-

Drive shaft end - float	.050/.076 mm. (.002/.004 in.)