

111 Class

Number 1970/26

Type

All models

Date

1.7.1970

LOTUS CARS (SERVICE) Ltd NORWICH NORFOLK NOR92W

Tel: WYMONDHAM 3411 CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager	Foreman		

Title:

Fuel Tank Sender Unit Special Locking Tool.

Reason:

Introduction of Special Tool to ensure that when tank

sender units are checked for leaks, or replaced, they can

be fully tightened.

Parts Required:

Sender Unit Special Tool

Part No. A036 T 6015

Price:

A036 T 6015

19s. 3d. (96p.) U.K. recommended

retail

Charges:

U.K.

- Warranty.....NO

EXPORT - FactoryNO

- DistributorNO

Action:

When the occassion arises (i.e. replacement or, when

checking the fuel system for leaks on the P.D.I.), use the Special Tool to check that the fuel tank sender unit

is fully tightened and thus, not leaking.