



# Lotus Service Bulletin

CLASS: 111  
NUMBER: 1973/01  
TYPE: All Europa TC  
Date: January 1973

LOTUS CARS Ltd - NORWICH NORFOLK NOR92W - Tel: WYMONDHAM 3411 - CABLES LOTUS NORWICH TELEX 97401

Circulation List	Service Manager		Foreman			
------------------	-----------------	--	---------	--	--	--

Title: Handbrake

Reason: Extra Adjustment

Action: To reduce the frequency of the handbrake adjustment, the travel may be increased by the following simple action.

1. Disconnect the cable and remove the handbrake.
2. Cut of the boss at the end of the barrel (see illustration)
3. Replace the handbrake, re-connect the cable and adjust as required.

