

Lotus Europa S1/S2 Parts Manual - Section BM - Body - Replacement Fiberglass Section 2 - Page 2

| Item | Lotus # | S1 | S1AB | S2 | S2 Fed | TC | TC Fed | TCS | TCS F | СНО | RHD | Description | Change Point Notes Bulletin Reference |
|------|-----------|----|------|----|--------|----|--------|-----|-------|-----|-----|---|---|
| 1 | 046B6101 | 1 | 1 | | | | | | | | | Full Rear Section | Up to Chassis No. 0542 |
| 1 | 054B6043 | | | 1 | 1 | | | | | | | Full Rear Section | From Chassis No. 0543 |
| 2 | 046B6103 | 1 | 1 | | | | | | | | | Half Full Rear LH | Up to Chassis No. 0542 |
| 2 | 054B6045 | | | 1 | 1 | | | | | | | Half Full Rear LH | From Chassis No. 0543 |
| 3 | 046B6102 | 1 | 1 | | | | | | | | | Half Full Rear RH | Up to Chassis No. 0542 |
| 3 | 054B6044 | | | 1 | 1 | | | | | | | Half Full Rear RH | From Chassis No. 0543 |
| 4 | 046B6100 | 1 | 1 | | | | | | | | | Short Rear | Up to Chassis No. 0542 |
| 4 | 054B6046 | | | 1 | 1 | | | | | | | Short Rear | From Chassis No. 0543 |
| 5 | 046B6099 | 1 | 1 | | | | | | | | | Half Short Rear LH | Up to Chassis No. 0542 |
| 5 | 054B6047 | | | 1 | 1 | | | | | | | Half Short Rear LH | From Chassis No. 0543 |
| 6 | 046B6098 | 1 | 1 | | | | | | | | | Half Short Rear RH | Up to Chassis No. 0542 |
| 6 | 054B6048 | | | 1 | 1 | | | | | | | Half Short Rear RH | From Chassis No. 0543 |
| 7 | A046B6138 | 1 | 1 | 1 | 1 | | | | | | | Roof Panel including Windscreen Pillars | |