


MH



Lotus Europa S1/S2 Parts Manual - Section MH - Electrical - Radio - Page 2

Item	Lotus #	S1	S1A/B	S2	S2 Fed	TC	TC Fed	TCS	TCS F	LHD	RHD	Description	Change Point Notes Bulletin Reference
1	046B6034											Replaced by 054M6039 with 1 of 054M6046 - 1 of 054M6047 - 1 of 054M6048	SB - Service III 1969/28
1	046B6035											Replaced by 054M6039	
1	054M6039	1	1	1								Radio Receiver	
1	054M6040				1							Radio Receiver	
2	054M6047			1	1							Aerial	
3	054M6046			1	1							Speaker - Radio	
4	054M0110			1	1							Suppression Plate	
5	054M0111			1	1							Suppression Plate	
5	XUFB0432			2	2							Bolt - Suppression Plate to Bulkhead	
5	A04W0904			4	4							Washer - Suppression Plate to Bulkhead	
5	YUFN040F			1	1							Nut - Suppression Plate to Bulkhead	
5	054M6148	1	1	1	1							Fitting and Suppression Kit	