


MB



Item	Lotus #	S1	S1A/B	S2	S2 Fed	TC	TC Fed	TCS	TCS F	LHD	RHD	Description	Change Point Notes Bulletin Reference
1	A074M6002W					2		2		+		Assembly - Headlamps	
1	A054M6064W					2				+		Assembly - Headlamp (replaced by A074M6002W)	
1	X046M6197W					2		2			+	Assembly - Headlamp (clear bulb and pilot bulb)	
1	A054M6061W					2		2			+	Assembly - Headlamp (yellow bulb and pilot bulb)	
1	A036M6078W					2		2			+	Assembly - Headlamp (clear bulb only)	
1	A036M6302W						2		2			Assembly - Headlamp	
2	X046M6185Z					2		2				Unit - Lamp - Headlamp	
3	X036M6081Z					2		2		+		Unit - Lamp - Headlamp	
3	X036M6083Z						2		2			Unit - Lamp - Headlamp	
4	X046M6187Z					4	4	4	4			Screw - Trimmer - Headlamp Assembly	
5	X036M6036Z					2	2	2	2			Headlamp Bezel	
6	X046M6163Z					2	2	2	2			Headlamp Rim	
6	X046M6162Z					2	2	2	2			Headlamp Assembly Gasket	
7	X036M6044Z					2	2	2	2			Headlamp Assembly Gasket	
8	X036M6360Z					2		2			+	Bulb (? #) - Clear - Headlamp Assembly	
9	A036M6361Z					2		2			+	Bulb (? #) - Yellow - Headlamp Assembly	
10	A036M6330Z					2		2		+	+	Bulb (989) - Pilot - Headlamp Assembly	
10	RSTS1014					8	8	8	8			Screw - Headlamp Mounting	
10	X036B6004Z					8	8	8	8			Nut - Headlamp Mounting	